ECS Configuration Change Request

Page 1 of   Page(s)

1. Originator	2. Log Date:	3. CCR #:	4. Rev:	5. Tel:	6. Rm #:	7. Dept.
Sarah Lewallen	**7/11/02**	**02-0579**	—	301-925-0865	2117B	SED

8. CCR Title: Move Sun 3000 t1pls01 to the PVC rename as p2mss20 for Dashboard

9. Originator Signature/Date	10. Class	11. Type:	12. Need Date: 8/12/02
Sarah Lewallen /s/ 7/11/02	**II**	**CCR**	

13. Office Manager Signature/Date	14. Category of Change:	15. Priority: (If "Emergency" fill in Block 27).
James R. Mather /s/ 7/11/02	Update ECS Baseline Doc.	Routine

16. Documentation/Drawings Impacted: see attached	17. Schedule Impact:	18. CI(s) Affected:MSSHW

19. Release Affected by this Change: 6A, 6B	20. Date due to Customer:	21. Estimated Cost: None - Under 100K

22. Source Reference: ☐NCR (attach)   ☐Action Item   ☐Tech Ref.   ☐GSFC   ☒Other:
Dashboard platform needed in PVC

23. Problem: (use additional Sheets if necessary)
A system is needed for Dashboard in the PVC.

24. Proposed Solution: (use additional sheets if necessary)
Move the old t1pls01 from the VATC and reconfigure in the PVC as p2mss20. Connect the A5200 RAID which was procured for this system. Configure with Solais 8 and COTS and CUSTOM that is baselined for Dashboard.

25. Alternate Solution: (use additional sheets if necessary)
None

26. Consequences if Change(s) are not approved: (use additional Sheets if necessary)
Will not have the dashboard platform in the PVC.

27. Justification for Emergency (If Block 15 is "Emergency"):

28. Site(s) Affected: ☐EDF   ☒PVC   ☒VATC   ☐EDC   ☐ GSFC ☐LaRC   ☐NSIDC   ☐SMC ☐AK ☐JPL
☐EOC   ☐ IDG Test Cell   ☐Other

29. Board Comments:	30. Work Assigned To:	31. CCR Closed Date:

32. EDF/SCDV CCB Chair (Sign/Date): **Otai Harley /s/ 7/17/02** Byron V. Peters /s/ 7/11/02	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB

33. M&O CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ECS

34. ECS CCB Chair (Sign/Date):	Disposition: Approved App/Com. Disapproved Withdraw Fwd/ESDIS ERB Fwd/ESDIS

CM01JA00 Revised 10/15/01   ECS/EDF/SCDV/M&O

ADDITIONAL SHEET

CCR #:   **02-0579**   **Rev: —**   **Originator:** Sarah Lewallen

Telephone: 301-925-0865   **Office:** 2117B

Title of Change: Move Sun 3000 t1pls01 to the PVC rename as p2mss20 for Dashboard

910-TDA-005 Site Host Map

PVC Documentation:
920-TDP-001 Hardware Diagram
920-TDP-002 Hardware-Software Map
921-TDP-002 Hardware Network Diagram
921-TDP-003 Host IP Assignments
921-TDP-004 IP Address Assignments
920-TDP-004 Floor Plan
920-TDP-005 Cable Management Plan
922-TDP-00x Disk Config for p2mss20
920-TDP-009 Database Host Map

VATC Documentation:
920-TDV-001 VATC Hardware Diagram
920-TDV-002 VATC Hardware-Software Map
921-TDV-002 Hardware Network Diagram
921-TDV-003 Host IP Assignments
921-TDV-004 IP Address Assignments
920-TDV-004 Floor Plan
920-TDV-005 Cable Management Plan
922-TDV-013 Disk Partition Diagram - retire this document.

Follow COTS Release Notes: 914-TDA-192 Rev 01 - Java and Web Services COTS Maintenance Upgrade for Solaris 8
Note on page 6-1, the PVC host will be p2mss20.

Solaris 8 02/02 as configured by Jumpstart, Apache 1.3.26, Tomcat 3.2.3, jConnect 5.2, PopChart 3.8 (use license from the SMC), Forte 6.1, jre 1.3.1_01, ssh client 2.4, ssh server 1.3.7, Sybase ASE 11.9.2 EBF9741, VM 3.0.4, Tripwire 1.3.1, FIND_DOS 4.2, Jet Direct 3.10.18, Legato Networker Client 6.0.2 Build 251, PERL 5.6.1, SQL 4.3.4, TCL/tk 8.3.3, TCP wrappers 7.6, Tivioli Client 3.6.3